

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- 1. Name of the Officer GEORGE ZACHARIA
- 2. Name of the School ST. GEORGE PUBLIC SCHOOL
- 3. Location with name of Education District/ Sub. District MANNOOR, MUVATTUPUZHA
- 4. Classification of Building as specified in column 4 of the application for fitness certificate and size. RCC

L-shaped 1) 59.70m x 7.90m x 3.66m (Ground Floor)
 L-shaped 2) 59.70m x 7.90m x 3.66m (First Floor)
 L-shaped 3) 59.70m x 7.90m x 3.66m (Second Floor)

- 5. Period for which the certificate is issued 2024-2025
- 6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
- 7. Any major defects noticed which will render the building unsafe in any manner NIL
- 8. Whether maintenance works have been done properly NIL
- 9. Whether the structure is sound or not for conducting classes Yes

} NIL
 } NIL
 } Yes

Yes, sound under normal weather and wind conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 24/05/2024 and found to be fit / ~~unfit~~ to conduct classes, for the period 2024-2025 for the reasons stated above.

Place: Airapuram
Date: 24/05/2024



[Signature]
24/05/2024

Assistant Engineer
എൽ.എ.സി. & ഇ ഡബ്ല്യു സെക്ഷൻ
മുഖ്യവനാശ്ശർ ബി.പി, കോടാപുരം - 683541